

Cohesion FLOOR CARE SYSTEM

- High Shine
- Low Maintenance
- No Burnishing No Stripping
- LESS Scratching Scuffing Black Marking



Cohesion Floor Care System

Description: Cohesion Floor Coating is a new generation finish designed to reduce maintenance. It is a self polishing finish when regularly cleaned with an automatic floor scrubber and Cohesion SBR using an appropriate Clean and Polish* pad.



Cohesion Floor Coating - High Shine, Low Maintenance

- High Solids with great initial shine
- Less Scratching, scuffing and black marking
- · No Burnishing or Stripping Required
- Part# 904045 Case of 2 x 2.5G



Cohesion 8 SBR - Clean & Polish Maintainer

- Works with Clean & Polish pads to remove soil and build gloss
- Gloss gradually builds with each cleaning
- · Save labor...No need to burnish
- •Part# 908922

Maintenance: Cohesion Floor Coating was designed to be maintained with no burnishing. Regular cleaning using Multi-Clean's Cohesion SBR in an automatic scrubber equipped with a Clean and Polish* pad is all that is needed to maintain a clean and glossy surface. Dust mopping regularly and ample walk off matting at entrances will keep the finish looking pristine.



Clean and Polish Daily Maintenance Floor Pads -

- For daily autoscrubbing with SBR
- * 3M[®] Clean & Shine™ Pads
- * Americo® Smart Scrub™ Scrub & Shine

 These pads are available from your local distributor



Cohesion 9 Intensity - Recoat Prep

- Works with surface prep pads** to remove multiple layers of old finish
- Intensive cleaning to remove deeply embedded dirt
- · Leaves a clean prepared surface for recoating
- · Save labor...No need to strip
- •Part# 908632
- ** 3M® SPP Pads
- ** Americo® Marroon EcoPrep "EPP" Pad

 These pads are available from your local distributor

Cohesion Floor Care Process

floor finishes that are in good condition.



Part# 904045

Apply up to 4 coats of Cohesion Floor Coating. Allow 20-40 minutes dry time per coat depending on conditions.

First Application:

Cohesion Floor Coating

Cohesion SBR Daily Clean and Polish

Maintain with Cohesion SBR and an automatic scrubber equipped with a clean and polish pad*. Dust mop regularly and using ample walk off matting at entrances.

Prep the surface as described below for recoating, or completely strip off old finish if needed. Cohesion Floor Coating can be applied over existing









How it Works: Mix Cohesion SBR in your scrubber at a rate of 1-2 oz per gallon of water. Equip the scrubber with a recommended clean and polish* pad. Always dust mop before scrubbing. Scrub your floor daily to maintain a clean and shiny surface. Gloss will increase with regular scrubbing. Optional High Speed Burnishing: Cohesion Floor Coating can be burnished if desired, but burnishing is not required.



Part# 908922

Cohesion Intensity Recoat Prep with no Stripping

Prep floors for recoating with Cohesion Intensity in an automatic scrubber equipped with a surface prep pad**.







How it Works: Mix Cohesion Intensity in your scrubber at a rate of 2 oz per gallon of water. Equip the scrubber with a recommended surface prep pad. Scrub the entire floor using a generous amount of cleaning solution. Hand scrub corners and edges. Rotary or orbital action floor machines both also work exceptionally well.

TIP: Change the surface prep pad regularly to obtain best results. Flip the pad every 5000 sq ft and change the pad after scrubbing 10,000 sq. ft.



Part# 908632

Cohesion FLOOR CARE SYSTEM



Ideal equipment for Cohesion Floor Care System includes walk behind and orbital floor scrubbers.

Cohesion [koh-hee-zhuhn] noun def. A group or team that works together in close harmony.





Ecoprep (EPP) and Surface Prep (SPP) pads are available in rectangular sizes for orbital scrubbers.

Contact Us: 600 Cardigan Road Shoreview Minnesota 651-481-1900

